

## Message Text

UNCLASSIFIED

PAGE 01 STATE 097340  
ORIGIN FAA-00

INFO OCT-01 ARA-14 ISO-00 EB-08 DOTE-00 /023 R

DRAFTED BY FAA/AIA-230:NJANSELL  
APPROVED BY EB/OA/AVP:GGRIFITHS  
EB/OA/AVP:JSGRAVATT  
ARA/CEN:DJOHNSON  
-----032272 151403Z /65

R 150337Z APR 78  
FM SECSTATE WASHDC  
TO AMEMBASSY SAN JOSE  
INFO FAA ATLANTA ASO-1F

UNCLAS STATE 097340

E.O. 11652: N/A

TAGS: EAIR, CS

SUBJECT:FAA TECHNICAL ASSISTANCE

1. PLEASE PASS FOLLOWING TO MR. WALDEN, FAA ENGINEER.  
QUOTE: DUE TO PERSONNEL SHORTAGE, FAA/W UNABLE TO PROVIDE  
SERVICES OF ATC ADVISOR TO RADAR SITING PROJECT.
2. FAA/W UNDERSTANDS THAT GOCR MAY ATTEMPT TO HIRE RETIRED  
FAA ATC SPECIALIST TO PROVIDE THESE SERVICES. HOWEVER, IN  
THE EVENT THAT THEY ARE NOT SUCCESSFUL, PLEASE BRING THE  
CURRENT APPROACH PLATES AND FUTURE ATC PLANS BACK TO FAA  
HEADQUARTERS FOR ANALYSIS. CHRISTOPHER

UNCLASSIFIED

NNN

## Message Attributes

**Automatic Decaptioning:** X  
**Capture Date:** 01 jan 1994  
**Channel Indicators:** n/a  
**Current Classification:** UNCLASSIFIED  
**Concepts:** TECHNICAL ASSISTANCE, CONSULTANTS  
**Control Number:** n/a  
**Copy:** SINGLE  
**Draft Date:** 15 apr 1978  
**Decaption Date:** 01 jan 1960  
**Decaption Note:**  
**Disposition Action:** n/a  
**Disposition Approved on Date:**  
**Disposition Case Number:** n/a  
**Disposition Comment:**  
**Disposition Date:** 01 jan 1960  
**Disposition Event:**  
**Disposition History:** n/a  
**Disposition Reason:**  
**Disposition Remarks:**  
**Document Number:** 1978STATE097340  
**Document Source:** CORE  
**Document Unique ID:** 00  
**Drafter:** 230:NJANSELL  
**Enclosure:** n/a  
**Executive Order:** N/A  
**Errors:** N/A  
**Expiration:**  
**Film Number:** D780162-0748  
**Format:** TEL  
**From:** STATE  
**Handling Restrictions:** n/a  
**Image Path:**  
**ISecure:** 1  
**Legacy Key:** link1978/newtext/t19780452/aaaabsci.tel  
**Line Count:** 43  
**Litigation Code IDs:**  
**Litigation Codes:**  
**Litigation History:**  
**Locator:** TEXT ON-LINE, ON MICROFILM  
**Message ID:** 1b1028ad-c288-dd11-92da-001cc4696bcc  
**Office:** ORIGIN FAA  
**Original Classification:** UNCLASSIFIED  
**Original Handling Restrictions:** n/a  
**Original Previous Classification:** n/a  
**Original Previous Handling Restrictions:** n/a  
**Page Count:** 1  
**Previous Channel Indicators:** n/a  
**Previous Classification:** n/a  
**Previous Handling Restrictions:** n/a  
**Reference:** n/a  
**Retention:** 0  
**Review Action:** RELEASED, APPROVED  
**Review Content Flags:**  
**Review Date:** 29 mar 2005  
**Review Event:**  
**Review Exemptions:** n/a  
**Review Media Identifier:**  
**Review Release Date:** N/A  
**Review Release Event:** n/a  
**Review Transfer Date:**  
**Review Withdrawn Fields:** n/a  
**SAS ID:** 2955283  
**Secure:** OPEN  
**Status:** NATIVE  
**Subject:** FAA TECHNICAL ASSISTANCE  
**TAGS:** EAIR, CS, US, FAA  
**To:** SAN JOSE  
**Type:** TE  
**vdkgvwkey:** odbc://SAS/SAS.dbo.SAS\_Docs/1b1028ad-c288-dd11-92da-001cc4696bcc  
**Review Markings:**  
Sheryl P. Walter  
Declassified/Released  
US Department of State  
EO Systematic Review  
20 Mar 2014  
**Markings:** Sheryl P. Walter Declassified/Released US Department of State EO Systematic Review 20 Mar 2014